


THIS VIEW IS
LOOKING INTO
DEIMOS



- NOTES:
1. Mahr gauge placement used for flexure tests on optical testbench.
 2. Reference Assembly P/N D4571 and D4671 Rev M.
 3. Dial indicator placement on Test plate.

SLIDER 4 TESTS 5-31-01 THROUGH 6-14-01
TEST BENCH GAUGE LOCATION DRAWING
file name: grating_test_plate_slider4

